

VOR/DME or TACAN RWY 24

VORTAC GXU 110.6 Chan 43	APCH CRS 243°	Rwy Idg 10,014 TDZE 117 Arpt Elev 141
--	-------------------------	--

AL-150 (USAF)
MC GUIRE FIELD (JOINT BASE MC GUIRE DIX LAKEHURST) (KWRI)

T * When ALS inop, increase CAT AB RVR to 55 and vis to 1 mile, CAT CDE vis to 1 1/2 miles.
** Circling NA SE of Rwy 24 and E of Rwy 36 when R-5001 A/B Active.




MISSED APPROACH: Climb to 2000 via GXU R-224 to DAMTE, Expect further clearance from ATC.


ATIS 110.6 270.1	MC GUIRE APP CON/DEP CON 126.475 363.8	TOWER 118.65 255.6	GND CON 121.8 275.8	CLNC DEL 135.2 335.8	PAR
---------------------	---	-----------------------	------------------------	-------------------------	-----

RADAR required when R-5001 and/or R-5002 is active.

If RADAR inoperative,
expect 15 minute delay
for deactivation of
R-5001 and/or R-5002.



EMERG SAFE ALT 100 NM 5100 FROM GXU VORTAC



HIRL all Rwy's
REIL Rwy's 18, 36
TDZL/CL Rwy 6

MC GUIRE FIELD (JOINT BASE MC GUIRE DIX LAKEHURST) (KWRI)

VOR/DME or TACAN RWY 24