

APP CRS	Rwy Idg	8000
101°	TDZE	815
	Apt Elev	815

RNAV (RNP) Z RWY 10L
JOHN GLENN COLUMBUS INTL (CMH)

RNP AR APCH.

Simultaneous approach authorized. For uncompensated Baro-VNAV systems, procedure NA below -19°C or above 54°C. For inop ALS, increase RNP 0.30 all Cnts visibility to RVR 6000.

MALSR

MISSED APPROACH:
Climb to 1400 then climbing left turn to 3000 direct APE
VORTAC and hold.

D-ATIS 124.6	COLUMBUS APP CON 125.95 371.975	COLUMBUS TOWER 132.7 257.8	GND CON 121.9 348.6	CLNC DEL 126.3	CPDLC
-----------------	------------------------------------	-------------------------------	------------------------	-------------------	-------

MISSED APCH FIX 4 NM

APPLETON APE

MSA RWY 10L 25 NM

3100

ELEV	815	TDZE	815
------	-----	------	-----

GP 3.00° TCH 50

See planview for multiple IF locations.

4.5 NM

CATEGORY	A	B	C	D
RNP 0.13 DA	1148/26 333 (400-⅓)			
RNP 0.26 DA	1198/35 383 (400-¾)			
RNP 0.30 DA	1216/40 401 (500-¾)			

AUTHORIZATION REQUIRED

TDZ/CL Rwy 10R-28L
HIRL Rwys 10R-28L and 10L-28R

EC-2, 22 FEB 2024 to 21 MAR 2024

EC-2, 22 FEB 2024 to 21 MAR 2024