

ILS or LOC RWY 34L
JACKSON-MEDGAR WILEY EVERS INTL (JAN)

MALSR 	MISSED APPROACH: Climb to 1200 then climbing right turn to 3000 on heading 070° and MHZ VORTAC R-134 to RAKIN INT/MHZ 16.5 DME and hold.
--	---

[illegible]

REIL Rws 16R and 34R
HIRL Rws 16L-34R and 16R-34L

FAF to MAP 4.4 NM

Knots	60	90	120	150	180
Min:Sec	4:24	2:56	2:12	1:46	1:28

Obstacle Data:

Obstacle	Height (ft)	Frequency (MHz)
1200	1200	-
3000	3000	070°
RAKIN	134	MHZ
DABEY	12.8	MHZ

Approach Path Data:

Heading	Altitude (ft)
159°	1800
339°	1800

Minimums Table:

Category	A	B	C	D	E
S-ILS 34L	529/18 200 (200-1/2)				
S-LOC 34L	840/40	511 (500-3/4)	840/55	511 (500-1)	
CIRCLING	880-1	900-1	900-1 1/2	960-2	1040-2 1/2
	534 (600-1)	554 (600-1)	554 (600-1 1/2)	614 (700-2)	694 (700-2 1/2)

JUCZU DME MINIMUMS #

S-LOC 34L	760/40	431 (500-3/4)
CIRCLING	880-1	900-1
	534 (600-1)	554 (600-1)
	900-1 1/2	960-2
	554 (600-1 1/2)	614 (700-2)
	1040-2 1/2	694 (700-2 1/2)